



Aviation Hazards

Francis Marion National Forest

**CAUTION: NOT ALL HAZARDS ARE IDENTIFIED.
THIS MAP IS INTENDED FOR REFERENCE ONLY.
USE SECTIONALS FOR NAVIGATION.**

- | | | | | | |
|--|---------------------------|--|----------------|--|---------------------------|
| | Hospital | | Limited Access | | Stream/River |
| | Helispots | | Highway | | MTR Lines |
| | Seed Orchard Helibase | | Major Road | | Utility Lines (80 Ft AGL) |
| | Heli-Dip | | Local Road | | Lake/Pond |
| | Route Check Points | | Minor Road | | Reservoir |
| | Towers Under 200 Ft (AGL) | | Other Road | | Airport Strip |
| | Towers Over 200 Ft (AGL) | | Ramp | | Francis Marion Boundary |
| | | | Ferry | | Forest Service Land |
| | | | Pedestrian Way | | |



Helispots	Lat NAD83	Long NAD83
H1	33 22.78	79 49.33
HD2	33 18.66	79 53.71
H3	33 18.54	79 49.35
HD4	33 13.74	79 53.97
H5	33 10.56	79 52.45
HD6	33 10.49	79 50.25
H7	33 11.76	79 47.52
D8	33 14.48	79 43.38
HD9	33 10.67	79 46.13
D10	33 07.49	79 42.47
HD12	33 12.01	79 38.24
H13	33 14.15	79 36.35
H14	33 12.02	79 37.02
H15	33 11.74	79 34.12
H16	33 12.63	79 29.89
HD18	33 07.22	79 26.46
H19	33 07.30	79 32.73
H20	33 07.58	79 35.17
D21	33 06.05	79 30.94
HD22	33 02.62	79 36.29
D23	33 03.39	79 37.81
HD25	32 58.50	79 46.38
H26	32 59.51	79 45.52
D27	33 00.74	79 42.37
D28	33 00.13	79 39.72
H29	32 59.76	79 39.54
D30	32 58.09	79 40.12
D31	33 08.61	79 37.75
D32	33 01.65	79 45.74
HD33	33 15.95	79 39.31
HD34	33 19.88	79 50.82
HD35	33 08.42	79 34.55
H36	33 07.61	79 35.14
HD37	33 05.24	79 31.36
H8	33 06.51	79 46.57

Disclaimer: The Forest Service uses the most current and complete data available. GIS data and product accuracy may vary. They may be developed from sources of differing accuracy, accurate only at certain scales, based on modeling or interpretation, incomplete while being created or revised, etc. Using GIS products for purposes other than those for which they were created, may yield inaccurate or misleading results. The Forest Service reserves the right to correct, update, modify, or replace, GIS products without notification. For more information, contact:

GIS Coordinator
USDA Forest Service
Francis Marion and Sumter National Forests
4931 Broad River Road
Columbia, SC 29212
(803) 561-4031